

Equipment Overview



Connection Instructions:



- 1 Switching Tool Stand
- 2 Sponge
- 3 Switching Tool Stand Plug
- 4 Down Scroll Key
- 5 Up Scroll Key
- 6 Receptacle 120 VAC
- 7 Power Switch
- 8 Soldering Iron Plug
- 9 Soldering iron

2-7 WDH 10T / WDH 20T

Thank you for placing your trust in our company by purchasing the Weller WDH 10T / WDH 20T Switching Tool Stand.

This product meets or exceeds the requirements established by Weller for superior performance, versatility and quality.

1. Cautions! / Warnings!

Please read these Operating Instructions and the attached Safety Information carefully prior to initial operation. Failure to observe the safety warnings may result in accident, injury, or risk to health.

The manufacturer shall not be liable for damage resulting from misuse of the machine or unauthorized alterations.

Warning: This product when used for soldering and similar applications, produces chemicals known to the State of California to cause cancer and birth defects or other reproductive harm.

Safety Information:

- 6 Always place the soldering iron in its original holder
- **©** Remove all inflammable objects from the proximity of the hot soldering tool.
- **10** Use suitable protective clothing to prevent the risk of burns associated with molten solder.
- **3** Never leave a soldering/desoldering tool unattended.
- O Never work on electrically live circuits or components.
- **3** Always wear eye protection when working with soldering and desoldering applications.

The Weller WDH 10T / WDH 20T Switching Tool Stand corresponds to the EC Declaration of Conformity in accordance with the basic safety requirements of Directives 89/336/EEC and 73/23EEC.

1.1 Additional Documents

- Operating Instructions of your control unit including the accompany booklet on Safety Instructions
- Operating Instructions of your soldering tool

1.2 Intended use

Always use the Switching Tool Stand WDH 10T / WDH 20T exclusively for placing the listed Sodering Tool, (See Technical Data) as specified in these Operating Instructions. Specified use of the Switching Tool Stand WDH 10T / WDH 20T also includes:

- observance of these Operating Instructions,
- observance of all other accompanying documentation,

WDH 10T / WDH 20T 3-7

observance of the locally applicable accident prevention regulations

The manufacturer shall not be liable for damage resulting from unauthorized alterations to the device.



The Weller WDH 10T / WDH 20T Switching Tool Stand, as opposed to a standard Tool Stand, provides a switching function that is activated by the soldering station. A microswitch integrated in the Switching Tool Stand is actuated when the soldering tool is placed in the holder or removed.

When the Switching Tool Stand is placed into a **Digital Weller Soldering Station** the Tool Stand and the Temperature SETBACK functions are automatically detected.

Several Switching Tool Stands can be connected together at the side.

Technical Data WDH 10T / WDH 20T

Dimensions L x W x H (inches): 8.189 x 2.56 x 4.53

L x W x H (mm): 208 x 65 x 115

Weight 1.52 lb. (0.69 kg)

Matching soldering WDH 10T: WP80, WSD161, WSD151,

tools WSP80

WDH 20T: WMP

Compatible WSD81, WSD161, WDD81V, WSL, WSL2, control units WAD101, WMRS, WRS1002, WRS3000,

WD1, WD2, WD1M, WD2M, WR 3M


3 Placing into Operation

WARNING! Risk of burns when working with soldering tools

There is a risk burning if you touch the hot soldering tool.



- 1. Carefully unpack the Switching Tool Stand.
- 2. Ensure that the soldering station to be connected to is off.
- Insert the 7-pin plug (3) of the Switching Tool Stand connecting cable at the soldering station tool receptacle and lock it by turning clockwise slightly.



4-7 WDH 10T / WDH 20T

- Place the soldering iron (9) in the Switching Tool Stand (1) and insert the soldering iron 7-pin plug (8) into the Switching Tool Stand receptacle and lock it by turning clockwise slightly.
- 5. Switch on the soldering station (7).

4 Operating Guidelines

4.1 Temperature decrease (SETBACK) and automatic switch-off time (AUTO-OFF) with connected Switching Tool Stand

The SETBACK time and AUTO-OFF time can be set at the control unit (WD1, WD2, WD1M, WD2M and WR 3M units), or are permanently specified (WSD and WRS units).

After placing the soldering tool in the Switching Tool Stand, the temperature decreases and/or the system shuts down, depending on the setting at the control unit. The respective switching action is displayed in the following table.

Tab. 1. Temperature and switch-off action of the control units WD1, WD2, WD1M, WD2M,

Tab. 2. WR 3M, WSD and WRS with different settings of the SETBACK and AUTO-OFF functions

Possible settings at the control unit ¹⁾		Temperature switching action after placing the soldering tool in the Switching Tool Stand
	OFF time [1-999 mins]	
0	0	The soldering tool is switched off in the holder ²⁾ .
ON	0	The soldering tool is regulated in the holder ²⁾ down to STANDBY temperature ³⁾ .
0	Time	The soldering tool is switched off in the holder ²⁾ after the OFF time has elapsed.
ON	Time	The soldering tool is regulated in the holder ²⁾ down to the STANDBY temperature ³⁾ and is switched off after the OFF time has elapsed.
Time	0	The soldering tool is regulated in the holder ²⁾ down to STANDBY temperature ³⁾ after the SETBACK time has elapsed.
Time	Time	The soldering tool is regulated in the holder ²⁾ down to the STANDBY temperature ³⁾ after the SETBACK time has elapsed and is switched off after the OFF time has elapsed.

¹⁾ With the WSD and WMD devices, only the settings 0/0 and ON/TIME are possible, whereby the respective time values for SETBACK (20 minutes) and AUTO-OFF (60 minutes) are permanently specified. With these device types, deviating SETBACK times are only possible with the external input device WCB2.

²⁾ Outside the Switching Tool Stand, the soldering tool always remains at the set specified temperature. The holder function is activated after the first time the soldering tool is deposited.

³⁾ The STANDBY temperature must be below the set specified temperature; otherwise the SETBACK function is inactive.

WDH 10T / WDH 20T 5-7

Note

Observe the Operating Instructions of your control unit when setting and switching the SETBACK and AUTO-OFF functions on and off.

4.2 Switching valve control with Switching Tool Stand on/off (WAD101)

When operating a soldering iron with inert gas and when using the Switching Tool Stand, the valve control must be set at the WAD 101 control unit. Two switching conditions are possible:

- A-1: the valve control is switched on. The valve is activated by the Switching Tool Stand with the ON/OFF function. In this operating condition, the SETBACK function "OFF" is not available.
- A-0: the valve control is switched off. The SETBACK function is available without restrictions.

Note

Observe the Operating Instructions of your control unit when setting the valve control function.

5 WDH 10T / WDH 20T: maintenance and care

The sponge should be cleaned regularly to remove solder residue using distilled water only.

6 Fault messages and corrective actions

G				
Message/Symptom	Possible cause	Corrective measures		
Soldering iron does not switch off after being placed	SETBACK time on the soldering station is activated	Soldering iron only switches off after the set time:		
in the holder		Set the SETBACK time on the soldering station to 0.		
	The holder is not correctly connected	▷ Check connecting cable		
		- Holder cable to soldering station		
		- Soldering iron to holder		
Soldering iron no longer switches on after removal from holder	Movable funnel or shift linkage is jammed	Check funnel and shift linkage		

6-7 WDH 10T / WDH 20T

7 Accessories

Dry cleaning insert WDC 2, 0051512599 Spiral wool, 0051382599

8 Packing List

WDH 10T

- 0051516199 Switching Tool Stand WDH 10T
- Operating Instructions WDH 10T / WDH 20T

WDH 20T

- 0051516299 Switching Tool Stand WDH 20T
- Operating Instructions WDH 10T / WDH 20T

9 Disposal

Dispose of replaced equipment parts, filters or old devices in accordance with the rules and regulations applicable in your country.

10 Warranty

Cooper Hand Tools warrants to the original purchaser and any subsequent owner ("Buyer") that Weller soldering and desoldering products will be free from defects in material and workmanship for a period of **one year** from date of purchase, provided that no warranty is made with respect to products which have been altered, subjected to abuse or improperly used, installed or repaired. Use of non-Cooper Hand Tools components will void this warranty if a non-Cooper Hand Tools component is defective (or is the source of the defect). Cooper Hand Tools will repair or replace products found to be defective not caused by a part, component or accessory manufactured by another company, during the warranty period. Contact Cooper Hand Tools with dated proof of purchase and return to Cooper Hand Tools, 1000 Lufkin Road, Apex, NC 27539. All costs of transportation and reinstallation shall be borne by Buyers.

IN NO EVENT SHALL COOPER HAND TOOLS BE LIABLE FOR INCIDENTAL OR CONSEQUENTIAL DAMAGES. COOPER HAND TOOLS LIABILITY FOR ANY CLAIMS ARISING OUT OF THIS WARRANTY SHALL NOT EXCEED THE PURCHASE PRICE OF THE PRODUCT.

THE PERIOD OF ALL IMPLIED WARRANTIES APPLICABLE TO THIS PRODUCT INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS, OR FITNESS FOR A PARTICULAR PURPOSE IS LIMITED TO 12 MONTHS FROM THE DATE OF PURCHASE BY THE USER.

WDH 10T / WDH 20T 7-7

Some states do not allow the exclusion or limitation of incidental or consequential damages, so the above limitation or exclusion may not apply to you. Some states do not allow limitation on how long an implied warranty lasts, so the above limitation may not apply to you.

This warranty gives you specific legal rights, and you may also have other rights, which vary, from state to state.

www.Cooperhandtools.com

Weller is a registered Trademark and registered Design of Cooper Industries, Inc.

U.S Mailing Address:

Cooper Hand Tools

P.O. Box 728

Apex, NC 27502-0728

U.S Shipping Address:

1000 Lufkin Road

Apex, N.C. 27539

Tel: (919) 387-0099

Fax: (919) 387-2379

For inquiries concerning Technical /

Customer Service please call:

(800) 476-3030 Ext. 1

Canada Shipping Address:

Cooper Tools

164 Innisfil Street

Barrie, Ontario

Canada L4N 3B7

Attn: Repairs

Fax: 1-800-403-TOOL (8665)

Phone: 705-728-5564 Ext. 2026

005 XX XXX XX / 03.07 © 2007 Cooper Industries