## QUICK START GUIDE FOR DEMONSTRATION CIRCUIT 811 DUAL OUTPUT LOW NOISE LDO REGULATORS

LT3027

## DESCRIPTION

Demonstration circuit 811 is a dual output and dual (independent) input regulator, based on the LT3027 IC, which consists of two identical LDO linear regulators in one package. Each input has an input voltage range of 2.3V to 20V, and either output is capable of delivering up to 100 mA of output current. The DC supply current, per channel, is typically only 20 uA at no load, and less than 0.1 uA in shutdown. The LT3027EDD comes in a small 10 Pin DFN package, which has an exposed pad on the bottom-side of the

IC for better thermal performance. The DC811 comes assembled with small ceramic capacitors, showing the LT3027 ability to maintain stability with ceramic output capacitors. These ceramic bypass capacitors are on each output for extra low noise performance. These features make the DC811 an ideal circuit for use in battery-powered, hand-held applications or noise sensitive applications. **Design files for this circuit board are available. Call the LTC Factory.** 

## **QUICK START PROCEDURE**

The DC811 is easy to set up to evaluate the performance of the LT3027. For proper measurement equipment configuration, set up the circuit according to the diagram in Figure 1.

Please follow the procedure outlined below for proper operation.

- 1. Connect the input power supply to the Vin and GND terminals. Connect the loads between the Vout and GND terminals. Refer to figure 1 for proper measurement equipment setup.
- 2. Before proceeding to operation, insert jumpers JP1 and JP2 into the OFF positions, and jumpers JP3 and JP4 into the voltage options of choice (2.5V, 3.3V, and 5V).
- 3. Apply 6.5V at Vin. Measure both Vouts; they should read 0V.
- 4. Turn on Vout1 and Vout2 by changing jumpers JP1 and JP2 from the OFF positions to the ON positions. Both output voltages should be within a tolerance of +/- 2%.

- 5. Vary the input voltage from 6.5V to 20V. Both output voltages should be within +/- 3.3% tolerance.
- 6. Vary each load current from 0 to 100mA. Both output voltages should be within a tolerance of +/- 4%.
- 7. Observe both output voltages AC-coupled; they should measure noise voltages of less than 2 mVAC each. Refer to Figure 2 for proper measurement technique.
- 8. When finished, insert jumpers JP1 and JP2 to the OFF position(s) and disconnect the power.

Warning - If the power for the demo board is carried in long leads, the input voltage at the part could "ring", which could affect the operation of the circuit or even exceed the maximum voltage rating of the IC. To eliminate the ringing, insert a small tantalum capacitor (for instance, an AVX part # TAJW106M025R) on the pads between the input power and return terminals on the bottom of the demo board. The (greater) ESR of the tantalum will dampen the (possible) ringing voltage due to the use of long input leads. On a normal, typical PCB, with short traces, the capacitor is not needed.

LINEAR

1




Figure 1. Proper Measurement Equipment Setup




Figure 2. Measuring Input or Output Ripple



## QUICK START GUIDE FOR DEMONSTRATION CIRCUIT 811 DUAL OUTPUT LOW NOISE LDO REGULATORS

