



Expertise Applied | Answers Delivered

8755 W. Higgins Road  
Suite 500  
Chicago, IL 60631 [www.littelfuse.com](http://www.littelfuse.com)

May 16<sup>th</sup>, 2013

**Inner Packaging Box Change for Radial Bulk Packing MOVs PCN# 3859E**

Dear Valued Customers,

Littelfuse would like to notify you of a change relating to inner packaging box for Radial Bulk packing MOVs effective from the Jun.16<sup>th</sup>, 2014.

After a complete qualification test, the qualification test result ensures that the new packaging box possess the same dimension, structure strength and environmental compliance as the existing packaging box. The original packing quantity will be remained with no changes. The complete qualification test reports are available upon request.

Please see the following photo of existing and new box and affected part number list;

**Existing Packaging Box**



**New Packaging Box**





Expertise Applied | Answers Delivered

8755 W. Higgins Road  
Suite 500  
Chicago, IL 60631 [www.littelfuse.com](http://www.littelfuse.com)

Affected part number listing:



20150515 Affected  
part number listi

Please respond to us by May 30<sup>th</sup>, 2014 to acknowledge notification of this change. If we do not hear from you then we will expect that this change has been accepted and no further action is required. Thank you!

Best Regards  
Johnny Chang  
Global Product Manager  
Littelfuse, Inc.  
[www.littelfuse.com](http://www.littelfuse.com)