

Male headers soldering technique

□ 0.5 mm, straight

	<p>S = 3,5 mm</p>			
<p>art. no.</p>	<p>dim. [mm]</p> <table border="1"> <thead> <tr> <th>A</th> <th>B</th> <th>C</th> </tr> </thead> </table>	A	B	C
A	B	C		
<p>SLY 1 081 ...</p>	<table border="1"> <tr> <td>8.10</td> <td>3.00</td> <td>3.60</td> </tr> </table>	8.10	3.00	3.60
8.10	3.00	3.60		
<p>SLY 1 085 ...</p>	<table border="1"> <tr> <td>8.50</td> <td>3.00</td> <td>4.00</td> </tr> </table>	8.50	3.00	4.00
8.50	3.00	4.00		
<p>SLY 1 098 ...</p>	<table border="1"> <tr> <td>9.80</td> <td>3.00</td> <td>5.30</td> </tr> </table>	9.80	3.00	5.30
9.80	3.00	5.30		
<p>SLY 1 104 ...</p>	<table border="1"> <tr> <td>10.40</td> <td>3.00</td> <td>5.90</td> </tr> </table>	10.40	3.00	5.90
10.40	3.00	5.90		
<p>SLY 1 139 ... G</p>	<table border="1"> <tr> <td>13.90</td> <td>3.00</td> <td>9.40</td> </tr> </table>	13.90	3.00	9.40
13.90	3.00	9.40		
<p>SLY 1 139 ... Z</p>	<table border="1"> <tr> <td>13.90</td> <td>3.00</td> <td>9.40</td> </tr> </table>	13.90	3.00	9.40
13.90	3.00	9.40		
<p>please indicate:</p> <p>... no. of contacts one row 1 - 50</p> <p>... surface S = selective gold-plated G = gold-plated Z = tin-plated</p>				
	<p>S = 3,5 mm</p>			
<p>art. no.</p>	<p>dim. [mm]</p> <table border="1"> <thead> <tr> <th>A</th> <th>B</th> <th>C</th> </tr> </thead> </table>	A	B	C
A	B	C		
<p>SLY 2 081 ...</p>	<table border="1"> <tr> <td>8.10</td> <td>3.00</td> <td>3.60</td> </tr> </table>	8.10	3.00	3.60
8.10	3.00	3.60		
<p>SLY 2 085 ...</p>	<table border="1"> <tr> <td>8.50</td> <td>3.00</td> <td>4.00</td> </tr> </table>	8.50	3.00	4.00
8.50	3.00	4.00		
<p>SLY 2 098 ...</p>	<table border="1"> <tr> <td>9.80</td> <td>3.00</td> <td>5.30</td> </tr> </table>	9.80	3.00	5.30
9.80	3.00	5.30		
<p>SLY 2 104 ...</p>	<table border="1"> <tr> <td>10.40</td> <td>3.00</td> <td>5.90</td> </tr> </table>	10.40	3.00	5.90
10.40	3.00	5.90		
<p>SLY 2 139 ... G</p>	<table border="1"> <tr> <td>13.90</td> <td>3.00</td> <td>9.40</td> </tr> </table>	13.90	3.00	9.40
13.90	3.00	9.40		
<p>SLY 2 139 ... Z</p>	<table border="1"> <tr> <td>13.90</td> <td>3.00</td> <td>9.40</td> </tr> </table>	13.90	3.00	9.40
13.90	3.00	9.40		
<p>please indicate:</p> <p>... no. of contacts two rows 4 - 100</p> <p>... surface S = selective gold-plated G = gold-plated Z = tin-plated</p>				